(X5) COMPLETION DATE

2/24/13

DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES QMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - MAIN BUILDING 01 B. WING 445017 01/07/2013 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2648 SEVIERVILLE RD ASBURY PLACE AT MARYVILLE

ľĎ

PREFIX

TAG

MARYVILLE, TN 37804

K 017 NFPA 101 LIFE SAFETY CODE STANDARD SS=D

(X4) ID

PRÉFIX

TAG

Corridors are separated from use areas by walls constructed with at least 1/2 hour fire resistance rating. In sprinklered buildings, partitions are only required to resist the passage of smoke. In non-sprinklered buildings, walls properly extend above the ceiling. (Corridor walls may terminate at the underside of ceilings where specifically permitted by Code. Charting and clerical stations, waiting areas, dining rooms, and activity spaces may be open to the corridor under certain conditions specified in the Code. Gift shops may be separated from corridors by non-fire rated walls if the gift shop is fully sprinklered.) 19.3.6.1, 19.3.6.2.1, 19.3.6.5

SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL

REGULATORY OR LSC IDENTIFYING INFORMATION)

This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure all fire wall construction is maintained.

The findings include:

Based on observation on January 7, 2013 from 2:15 p.m. and 4:30 p.m. revealed the following areas had penetrations or unapproved fire assembly in the fire rated wall.

- Above ceiling at fire doors by room 314
- Above ceiling at stalrwell door across from room 312
- Above ceiling at room 216.
- Above ceiling at fire doors by room 113
- Above ceiling at fire doors at one (1) south

K-017 - Areas #1 - #5 have or will K 017 be sealed with approved rated fire !

caulk by 2/24/13.

PROVIDER'S PLAN OF CORRECTION

(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE

DEFICIENCY)

A walk through audit of the building has been completed to identify any other penetrations.

The maintenance tech will conduct random audits throughout the building weekly for 4 weeks, then monthly for 3 months to check for any new penetrations.

The results of the audits will be reviewed at the Quality Assurance Committee (DON, Administrator, Facilities Director maintenance and housekeeping, MDS, Pharmacy, Social Services, Medical Director, ADON, Dining Services) meeting, beginning in February, monthly for three (3) months and recommendations implemented. as appropriate.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE

EXECUTATIVE DISCO Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation,

FORM CMS-2567(02-99) Previous Várstons Obsolete

Event ID: SX6C/21

Fectility ID: TN0505

If continuation sheet Page 1 of 4

DEPARTMENT OF HEALTH AND HUM.... IN SERVICES

FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED A, BUILDING 01 - MAIN BUILDING 01 B. WING_ 445017 01/07/2013 NAME OF PROVIDER OR SUPPLIED

NAME OF PROVIDER OR SUPPLIER ASBURY PLACE AT MARYVILLE		STREET ADDRESS, CITY, STATE, ZIP CODE 2648 SEVIERVILLE RD MARYVILLE, TN 37804		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	- (X5) COMPLETION DATE
K 017	elevator by Life Styles Office.	K 017	K-038 – The delayed egress door by room 140 was repaired on 1/8/13.	2/24/13
K 038 SS≂D		K 038	A random audit of remaining	
	This STANDARD is not met as evidenced by: Based on observation, the facility falled to assure exit access is readily accessible at all times.		The maintenance tech will conduct random audits throughout the building weekly for 4 weeks, then monthly for 3 months to check for proper functionality of delayed egress doors.	
1	The findings include: Observation on January 7, 2013 at 10:57 a.m. and 12:20 p.m. revealed that upon testing of the delayed egress door by room 140 did not alarm or open upon testing. The delayed egress doors	į	The delayed egress signage will be installed on the two doors identified on the first floor One North activity room.	,
	on the first floor one (1) North Activity room did not have delayed egress signage on two (2) of its doors.		A random audit of remaining delayed egress doors throughout the building was completed to	
K 056	These findings were verified by maintenance and acknowledged by the administrator during the exit conference on January 7, 2013, NFPA 101 LIFE SAFETY CODE STANDARD	K 056	check for proper signage. The maintenance tech will conduct random audits throughout the	
SS=D	If there is an automatic sprinkler system, it is installed in accordance with NFPA 13, Standard for the installation of Sprinkler Systems, to provide complete coverage for all portions of the		building weekly for 4 weeks, then monthly for 3 months to check for proper signage on the delayed egress doors.	

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED OMB NO. 0938-0391

		A MEDICALD SEIVAIOES				CIVIDITO	<u>. บของ-บอช 1</u>
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - MAIN BUILDING 01		(X3) DATE SURVEY COMPLETED		
		445017	a. Wil	NG		01/0	7/2013
	PROVIDER OR SUPPLIER PLACE AT MARYVIL	LE .		264	ET ADDRESS, CITY, STATE, ZIP CODE 8 SEVIERVILLE RD RYVILLE, TN 37804	1	
(X4) ID PREFIX TAG.	(EACH DEFICIENCY	ITEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION 8H: CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(%) COMPLETION DATE
K 058	building. The syste accordance with NF Inspection, Testing, Water-Based Fire F supervised. There supply for the syste systems are equipp	m Is properly maintained in FPA 25, Standard for the and Maintenance of Protection Systems. It is fully is a reliable, adequate water m. Required sprinkler ed with water flow and tamper electrically connected to the	K	056	The results of the audits we reviewed at the Quality As Committee (DON, Administracilities Director maintent and housekeeping, MDS, Pharmacy, Social Services, Director, ADON, Dining Semeeting, beginning in Febmonthly for three (3) mon recommendations implement as appropriate.	surance strator, ance Medical rvices) ruary, ths and	
SS=F	Based on observation the automatic sprint maintained. The findings include Observation on Januard 3:55 p.m. reveal emergency storage high to the ceiling of coverage. Above ce Plan Care Office wire supported by non synutomatic sprinkler: These findings were acknowledged by the conference on Januard NFPA 101 LIFE SAF Heating, ventillating, with the provisions of in accordance with the sprint of the secondance with the seco	uary 7, 2013 at 12:05 p.m. iled the three (3) day room has boxes stored too betructing the sprinkler illing in the corridor by the ing is attached to or retem components of the system. I verified by maintenance and e administrator during the exit ary 7, 2013. FETY CODE STANDARD and air conditioning comply if section 9.2 and are installed	K	987	K-056 – The storage room brought into compliance was proper storage and proper clearance of the sprinkler. The Director of Dining will random audits of the storage room weekly for 4 weeks, monthly for 3 months to compliance with proper clof the sprinkler system.	vith r system. conduct age then check for	1/7/13

DEPART MENT OF HEALTH AND HU.... IN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED OMB NO. 0938-0391

	OVIDER OR SUPPLIER PLACE AT MARYVIL SUMMARY STA	445017	B. WING_		01/07/2013	
ASBURY (X4) ID PREFIX	PLACE AT MARYVIL		D. T.			
IAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRÉCEDED BY FULL	20	REET ADDRESS, CHY, STATE, ZEP CODE 848 SEVIERVILLE RD IARYVILLE, TN 37804 PROVIDER'S PLAN OF CORRI (EACH CORRECTIVE ACTION SI	ECTION (XI	
	Continued From pa 19.5.2.2 This STANDARD is Based on record re naintain their Heati Conditioning (HVAC)	sc IDENTIFYING INFORMATION) Ige 3 In not met as evidenced by: Eview, the facility failed to Ing, Venting, and Air E).	K 067	K-067 – 25% of all listed son dampers will be properly to according to the standard of 2/24/13. The remaining first smoke dampers will be protested and maintained at a 25% each year over the 4-y maintenance requirement. An audit will be performed	PROPRIATE DAT	
T di	evealed that no 4-y naintenance has be 'his finding was ver irector and acknow	ear fire and smoke damper ear fire and smoke damper ear performed. Ifiled by the maintenance dedged by the administrator erence on January 7, 2013.		ensure that the 25% of smodampers were properly test according to standards. The results of the audits will reviewed at the Quality Ass Committee (DON, Administ Facilities Director maintena and housekeeping, MDS, Pharmacy, Social Services, MDirector, ADON, Dining Services, Mointena, beginning in February for three (3) month recommendations impleme as appropriate.	i be urance rator, nce /ledical rices) lary, as and	